

Athletics Outdoor – MacFinish 2D 400/410 – Basic Setup

(2018v1)



P519



Pxxx




2D 400 = P1100
2D 410 = P1101



P297



P294



MacFinish Software
PC not included

Legend

- Pxxx : Lens to be calculated
- P024 : MacFinish Arrival
- P041 : Battery Pack 12V 7AH
- P1031 : Carrying case MacFinish 2D
- P294 : Professional Tripod
- P297 : Professional Manual Geared Camera Head
- P519 : MacFinish 2D 100/400/410 Camera Protection hood
- P140 : MacFinish Ethernet 5m
- P934 : Battery Charger 110/220 Vac, 2,7 A
- P968 : Interfacebox MacFinish 2D 100/400/410

- P1100 : MacFinish 2D 400 camera
- or
- P1101 : MacFinish 2D 410 camera

Important remark 1:
Use the **P934 Battery Charger** as power supply for the MacFinish 2D 400 Interface Box!
Do not use the less powerful P72 Battery Charger for this.

- = 5-Pole Cable
- = 8-Pole Camera Cable
- = Ethernet Cable

Important remark 2:
Your MacFinish 2D 400/410 makes use of the latest **new firmware**. It is important that you work with our latest MacFinish **software 7.7.4.x** in order to work properly.